

## River Alliance of Wisconsin: Before and after images of Wisconsin Dam Removals

### 1. FRANKLIN DAM, SHEBOYGAN RIVER

Franklin Dam, Sheboygan River  
Removed 2001



Photo simulation of the Franklin Dam  
site after dam removal



Photos courtesy of the River Alliance of Wisconsin

Actual site 9 months after removal of the Franklin Dam



Photos courtesy of the River Alliance of Wisconsin

## 2. WILLOW FALLS DAM, WILLOW RIVER

Photo of Willow Falls Dam, Willow River  
Removed 1992



Site of former dam at Willow Falls,  
Willow River



Photos courtesy of the River Alliance of Wisconsin.

Former impoundment of Willow Falls  
Dam, 6 years later



Historical Willow Falls, 1800s



Photos courtesy of the River Alliance of Wisconsin.

### 3. WATERWORKS DAM, BARABOO RIVER

Waterworks Dam, Baraboo River  
Removed 1997-98



Waterworks Dam removal, Winter 97-98



Photos courtesy of the River Alliance of Wisconsin.

Waterworks impoundment,  
Baraboo River



Former Waterworks impoundment,  
Baraboo River  
12 months after removal



Photos courtesy of the River Alliance of Wisconsin.

#### 4. MOUNDS DAM, WILLOW RIVER

Photo of Mounds Dam, Willow River  
Removed 1998



Site of former Mounds Dam, Willow River



Photos courtesy of the River Alliance of Wisconsin.

Former impoundment of Mounds Dam,  
1 week after removal



Former impoundment of Mounds Dam,  
15 months after removal



Photos courtesy of the River Alliance of Wisconsin.



## 5. WOOLEN MILLS DAM, MILWAUKEE RIVER

Photo of Woolen Mills Dam,  
Milwaukee River. Removed 1988



Former impoundment of Woolen  
Mills Dam, 1 week after removal



Photos courtesy of the River Alliance of Wisconsin.

Former impoundment of Woolen Mills Dam, 12 years after removal.



Photos courtesy of the River Alliance of Wisconsin

## 6. WARD DAM, PRAIRIE RIVER

Photo of Ward Dam, Prairie River.  
Removed 1999



Former impoundment of Ward Dam, 2  
weeks after removal



Photos courtesy of the River Alliance of Wisconsin.

Former impoundment of Ward Dam, 1 year after removal



Former impoundment of Ward Dam, 2 years after removal



Photos courtesy of the River Alliance of Wisconsin.

## 7. COLFAX DAM, EIGHTEEN MILE CREEK

Colfax Dam



Removal Process, Winter 1998



Photos courtesy of the River Alliance of Wisconsin.

Former impoundment of Eighteen Mile  
Creek,  
immediately after removal



Former impoundment of Eighteen Mile  
Creek, 15 months after removal



Photos courtesy of the River Alliance of Wisconsin.